

RPi 4 EEPROM update 2021-12-14

```

pi@rpi64:~ $ sudo rpi-eeeprom-update
BOOTLOADER: up to date
  CURRENT: Thu 29 Apr 16:11:25 UTC 2021 (1619712685)
  LATEST: Thu 29 Apr 16:11:25 UTC 2021 (1619712685)
  RELEASE: default (/lib/firmware/raspberrypi/bootloader/default)
           Use raspi-config to change the release.

VL805_FW: Using bootloader EEPROM
  VL805: up to date
  CURRENT: 000138a1
  LATEST: 000138a1
pi@rpi64:~ $ sudo rpi-update
*** Raspberry Pi firmware updater by Hexxeh, enhanced by AndrewS and Dom
*** Performing self-update
*** Relaunching after update
*** Raspberry Pi firmware updater by Hexxeh, enhanced by AndrewS and Dom
*** We're running for the first time
*** Backing up files (this will take a few minutes)
*** Backing up firmware
*** Backing up modules 5.10.63-v8+
#####
WARNING: This update bumps to rpi-5.10.y linux tree
See: https://www.raspberrypi.org/forums/viewtopic.php?f=29&t=288234
'rpi-update' should only be used if there is a specific
reason to do so - for example, a request by a Raspberry Pi
engineer or if you want to help the testing effort
and are comfortable with restoring if there are regressions.

DO NOT use 'rpi-update' as part of a regular update process.

#####
Would you like to proceed? (y/N)
*** Downloading specific firmware revision (this will take a few minutes)
  % Total    % Received % Xferd  Average Speed   Time    Time     Time
Current
                                Dload  Upload  Total  Spent  Left
Speed
100  173  100  173    0    0   565      0  --:--:--  --:--:--  --:--:--
567
100 121M  100 121M    0    0  740k      0  0:02:48  0:02:48  --:--:--
716k
*** Updating firmware
*** Updating kernel modules
*** depmod 5.10.83-v8+
*** depmod 5.10.83-v7l+
*** depmod 5.10.83+
*** depmod 5.10.83-v7+

```

```
*** Updating VideoCore libraries
*** Using SoftFP libraries
*** Updating SDK
*** Running ldconfig
*** Storing current firmware revision
*** Deleting downloaded files
*** Syncing changes to disk
*** If no errors appeared, your firmware was successfully updated to
5b1fd2a67b10548cb95bc9b2f3feea8e3d23bc8e
*** A reboot is needed to activate the new firmware
```

From:
<https://rpi64-wired.seanys.com/> - **It's in The Wiki**

Permanent link:
https://rpi64-wired.seanys.com/rpi_4_eeprom_update

Last update: **2021/12/14 12:45**

